



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: VALENCIA_AVE		Cross Street: BIRCH_ST		Location:	SW
ADA ID: RPRK220201115812	Ramp Type: Blended Transition 1	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score:	20

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
---	--	--	---	--	--



Possible Solutions:

Remove & Replace Gutter. Relocate Obstruction. Utility Present.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, R302.3, R402.2, STD 1115

Total Cost: \$ 5252

Parcel ID Number	320-233-21	Street 1 Name	VALENCIA_AVE
Ramp Island Or Median	None	Stop Condition-Street 1	Signal
Ramp Orientation	Diag	Street 2 Name	BIRCH_ST
Google Street View Link:		Stop Condition-Street 2	Signal

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.91828628,-117.84805699

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
No	Obstructions Present?	Yes	N/A	Utilities Present?	Yes
	Obstruction Types	Pushbutton Post		Utility Types	
	Obstruction Dimensions	N/A		Pull Box	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	113	N/A	Flare Slope LT (%)	4.7
Yes	Ramp Width (in)	197	N/A	Flare Traversable LT	No
Yes	Ramp Run Slope (%)	4.2	N/A	Flare Slope RT (%)	6.5
Yes	Ramp Cross Slope (%)	1.8	N/A	Flare Traversable RT	No
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
Yes	Landing Length (in)	82	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	144	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	0.9	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	0.9		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	Yes			
Yes	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	E		Crossing 2 Direction	N
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	144
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	5		Crossing 2 Slope (%)	3.5
	Crossing 1 Cross Slope (%)	3.7		Crossing 2 Cross Slope (%)	0.1
Yes	Gutter Ponding	No	Yes	Curb Slope	0.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.9
Yes	Gutter Run Slope (%)	3.2		Road Cross Slope (%)	6.6
No	Gutter Cross Slope (%)	4			
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

