



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LAMBERT_RD Cross Street: VALENCIA_AVE Location: NW

ADA ID: RPRK220201121516 Ramp Type: Blended Transition 1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Relocate Obstruction. Utility Present.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R302.3, R402.2, STD 1115

Total Cost: \$ 8080

Parcel ID Number **320-073-09**
Ramp Island Or Median **None**
Ramp Orientation **Diag**
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.92431601,-117.84786149

Street 1 Name **LAMBERT_RD**
Stop Condition-Street 1 **Signal**
Street 2 Name **VALENCIA_AVE**
Stop Condition-Street 2 **Signal**

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
No	Obstructions Present?	Yes	N/A	Utilities Present?	Yes
	Obstruction Types	Pushbutton Post		Utility Types	
	Obstruction Dimensions	N/A		Pull Box; Traffic Signal Pole	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	65	N/A	Flare Slope LT (%)	4.5
Yes	Ramp Width (in)	172	N/A	Flare Traversable LT	No
No	Ramp Run Slope (%)	5.6	N/A	Flare Slope RT (%)	3.6
Yes	Ramp Cross Slope (%)	1.2	N/A	Flare Traversable RT	No
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
No	Landing Length (in)	48	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	70	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	1.2	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	0.6		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	Yes	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	Yes			
Yes	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	S		Crossing 2 Direction	E
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	144
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	2.2		Crossing 2 Slope (%)	0.4
	Crossing 1 Cross Slope (%)	2.3		Crossing 2 Cross Slope (%)	2.5
Yes	Gutter Ponding	No	No	Curb Slope	5.4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	1.4
Yes	Gutter Run Slope (%)	1.2		Road Cross Slope (%)	1
Yes	Gutter Cross Slope (%)	0.3			
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

