



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: BEACH_BLVD Cross Street: HAZARD_RD Location: SW

ADA ID: RPRK220202123003 Ramp Type: Type 6 - Directional 1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. Relocate Obstruction. Utility Present.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.5.4, R304.5.3, R302.3, R402.2, STD 1115

Total Cost: \$ 8332

Parcel ID Number 096-370-31
Ramp Island Or Median None
Ramp Orientation Diag
Google Street View Link:

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.75194991,-117.98977688

Street 1 Name BEACH_BLVD
Stop Condition-Street 1 Signal
Street 2 Name HAZARD_RD
Stop Condition-Street 2 Signal

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
No	Obstructions Present?	Yes	N/A	Utilities Present?	Yes
	Obstruction Types	Traffic Signal Pole		Utility Types	
	Obstruction Dimensions	N/A		Pull Box	

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	189	N/A	Flare Type LT	
Yes	Ramp Width (in)	76			Sloped
Yes	Ramp Run Slope (%)	5.2	Yes	Flare Slope LT (%)	6.1
Yes	Ramp Cross Slope (%)	0.3	N/A	Flare Traversable LT	Yes
Yes	Grade Break	Yes	Yes	Flare Type RT	
Yes	Grade Break Slope (%)	2			Curbed2
Yes	Grade Break Cross Slope (%)	1.2	N/A	Flare Slope RT (%)	N/A
	Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A
	Addl Para Ramp Right?	No	Yes	DWS Provided	Yes
N/A	Landing Present	Yes	Yes	DWS Contrast	Yes
Yes	Landing Length (in)	72	Yes	DWS Length (in)	96
Yes	Landing Width (in)	86	Yes	DWS Full Width	Yes
Yes	Landing Run Slope (%)	0.9		DWS Offset Type	Single
Yes	Landing Cross Slope (%)	2.3	Yes	DWS Left Offset (in)	0
N/A	Landing Movement Obstructed?	No	N/A	DWS Right Offset (in)	0
	Landing Movement Type	N/A			
N/A	Landing Shared	No			
N/A	Marked Crosswalk 1	Yes	Yes	Clear Space	Yes
	Crossing 1 Direction	SE	Yes	Clear Space To Crosswalk (in)	48
	Marked Crosswalk 1 Width (in)	144			
Yes	Ramp Inside Crosswalk 1	Yes			
	Crossing 1 Slope (%)	5.9			
	Crossing 1 Cross Slope (%)	0.9			
Yes	Gutter Ponding	No	Yes	Curb Slope	4.4
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	2.5
No	Gutter Run Slope (%)	6.3		Road Cross Slope (%)	2
No	Gutter Cross Slope (%)	3.1		Parallel Ramp Side	Right
Yes	Overall Surface Condition	Acceptable	No	Perp Joint Present	No
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

