



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: BOLSA_AVE **Cross Street:** BEACH_BLV **Location:** NW

ADA ID: RPRK220202161230 **Ramp Type:** Type 4 - Parallel **Initial Pass/Fail:** Pass **Overall Compliance:** No **Severity Score:** 5

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Detectable Warning System.

Surveyor Notes:
 N/A

OC Std/PROW:
R305.1.3, STD 1115

Total Cost: \$ 800

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	107	N/A	Ramp Length RT (in)	112
Yes	Ramp Width LT (in)	74	Yes	Ramp Width RT (in)	74
Yes	Ramp Run Slope LT (%)	2.1	Yes	Ramp Run Slope RT (%)	4.7
Yes	Ramp Cross Slope LT (%)	1	Yes	Ramp Cross Slope RT (%)	1.4
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
N/A	Landing Length (in)	74	No	DWS Contrast	No
Yes	Landing Width (in)	48	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	0.8	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	0.3		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
Yes	Clear Space	Yes			
Yes	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	S		Crossing 2 Direction	E
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	144
Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	2.2		Crossing 2 Slope (%)	3.7
	Crossing 1 Cross Slope (%)	0.1		Crossing 2 Cross Slope (%)	1.1
Yes	Gutter Ponding	No	Yes	Curb Slope	1.3
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.1
Yes	Gutter Run Slope (%)	1		Road Cross Slope (%)	1.1
Yes	Gutter Cross Slope (%)	0.6	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	No		Replace Spandrel?	No

Parcel ID Number: 096-370-35
Ramp Island Or Median: None
Ramp Orientation: Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74484015,-117.98971336

Street 1 Name: BOLSA_AVE
Stop Condition-Street 1: Signal
Street 2 Name: BEACH_BLV
Stop Condition-Street 2: Signal

Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

