



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: NEWLAND_ST Cross Street: MADISON_AVE Location: SW

ADA ID: RPRK220203131054 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 2

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance



Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
N/A

OC Std/PROW:
R304.5.3, STD 1115

Total Cost: \$ 4000

Parcel ID Number 097-154-23
Ramp Island Or Median None
Ramp Orientation Diag
Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74833739,-117.98107692

Street 1 Name NEWLAND_ST
Stop Condition-Street 1 Signal
Street 2 Name MADISON_AVE
Stop Condition-Street 2 Signal

Obstruction and Utility Measurement/Component Compliance			
Compliance	Description	Data	Compliance Description Data
Yes	Obstructions Present?	No	N/A Utilities Present? Yes
	Obstruction Types	N/A	Utility Types
	Obstruction Dimensions	N/A	Pull Box; Push Button; Traffic Signal Pole

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	92	N/A	Ramp Length RT (in)	113
Yes	Ramp Width LT (in)	150	Yes	Ramp Width RT (in)	150
Yes	Ramp Run Slope LT (%)	5.1	Yes	Ramp Run Slope RT (%)	7.5
No	Ramp Cross Slope LT (%)	4.4	No	Ramp Cross Slope RT (%)	3.9
N/A	Landing Present	N/A	N/A	DWS Provided	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Contrast	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing Run Slope (%)	N/A	N/A	DWS Full Width	N/A
N/A	Landing Cross Slope (%)	N/A		DWS Offset Type	N/A
N/A	Landing Movement Obstructed?	N/A	N/A	DWS Offset Left (in)	N/A
	Landing Movement Type	N/A	N/A	DWS Offset Right (in)	N/A
N/A	Landing Shared	N/A			
N/A	Clear Space	Yes			
N/A	Clear Space To Crosswalk (in)	48			
N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	Yes
	Crossing 1 Direction	E		Crossing 2 Direction	N
	Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	144
N/A	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	Yes
	Crossing 1 Slope (%)	3.7		Crossing 2 Slope (%)	3.5
	Crossing 1 Cross Slope (%)	1.2		Crossing 2 Cross Slope (%)	3.6
N/A	Gutter Ponding	N/A	N/A	Curb Slope	1.9
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	3
N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	4.2
N/A	Gutter Cross Slope (%)	N/A	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	Yes		Spandrel Present?	Yes
	Replace Cross Gutter?	No		Replace Spandrel?	No

