



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A Cross Street: PUERTO\_PL Location: E

ADA ID: RPRK220208152704 Ramp Type: Type 1 - Perpendicular Initial Pass/Fail: Pass Overall Compliance: Yes Severity Score: 0

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Possible Solutions:

N/A

Surveyor Notes:

N/A

OC Std/PROW:

N/A

Total Cost:

\$ 0

Parcel ID Number 682-023-03  
Ramp Island Or Median None  
Ramp Orientation NonDiag  
Google Street View Link:

[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.46199806,-117.6895677](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.46199806,-117.6895677)

Street 1 Name N/A  
Stop Condition-Street 1 NoControl  
Street 2 Name PUERTO\_PL  
Stop Condition-Street 2 N/A

## Obstruction and Utility Measurement/Component Compliance

| Compliance | Description            | Data | Compliance | Description        | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes        | Obstructions Present?  | No   | N/A        | Utilities Present? | No   |
|            | Obstruction Types      | N/A  |            | Utility Types      |      |
|            | Obstruction Dimensions | N/A  |            |                    | N/A  |

| Compliance | Description                           | Data | Compliance | Description                   | Data    |
|------------|---------------------------------------|------|------------|-------------------------------|---------|
| N/A        | Ramp Length (in)                      | 90   | Yes        | Flare Type LT                 |         |
| Yes        | Ramp Width (in)                       | 70   |            |                               | Curbed2 |
| Yes        | Ramp Run Slope (%)                    | 3.9  | N/A        | Flare Slope LT (%)            | N/A     |
| Yes        | Ramp Cross Slope (%)                  | 1.4  | N/A        | Flare Traversable LT          | N/A     |
| N/A        | Landing Present                       | Yes  | N/A        | Flare Type RT                 |         |
| N/A        | Landing Length (in)                   | 60   |            |                               | None    |
| Yes        | Landing Width (in)                    | 78   | N/A        | Flare Slope RT (%)            | N/A     |
| Yes        | Landing Run Slope (%)                 | 1.2  | N/A        | Flare Traversable RT          | N/A     |
| Yes        | Landing Cross Slope (%)               | 2    | Yes        | DWS Provided                  | Yes     |
| N/A        | Landing Movement Obstructed?          | No   | Yes        | DWS Contrast                  | Yes     |
|            | Landing Movement Type                 | N/A  | Yes        | DWS Length (in)               | 36      |
| N/A        | Landing Shared                        | Yes  | Yes        | DWS Full Width                | Yes     |
| N/A        | Clear Space                           | N/A  | Yes        | DWS Offset Left (in)          | 0       |
| N/A        | Clear Space To Crosswalk (in)         | N/A  | Yes        | DWS Offset Right (in)         | N/A     |
| N/A        | Marked Crosswalk 1                    | No   | N/A        | Marked Crosswalk 2            | N/A     |
|            | Crossing 1 Direction                  | N    |            | Crossing 2 Direction          | N/A     |
|            | Marked Crosswalk 1 Width (in)         | N/A  |            | Marked Crosswalk 2 Width (in) | N/A     |
| N/A        | Ramp Inside Crosswalk 1               | N/A  | Yes        | Ramp Inside Crosswalk 2       | N/A     |
|            | Crossing 1 Slope (%)                  | 2.2  |            | Crossing 2 Slope (%)          | N/A     |
|            | Crossing 1 Cross Slope (%)            | 1.8  |            | Crossing 2 Cross Slope (%)    | N/A     |
| Yes        | Gutter Ponding                        | No   | Yes        | Curb Slope                    | 0.6     |
| Yes        | Gutter Lip Height (in)                | 0    |            | Road Run Slope (%)            | N/A     |
| Yes        | Gutter Run Slope (%)                  | 3.6  |            | Road Cross Slope (%)          | N/A     |
| Yes        | Gutter Cross Slope (%)                | 0.1  |            |                               |         |
| Yes        | Overall Surface Condition: Acceptable |      | Yes        | Perp Joint Present            | Yes     |
|            | Cross Gutter Present?                 | Yes  |            | Spandrel Present?             | No      |
|            | Replace Cross Gutter?                 | No   |            | Replace Spandrel?             | N/A     |

