



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: STREET_OF_THE_GOLDEN_LANTERN Cross Street: STREET_OF_THE_GOLDEN_LANTERN Location: E

ADA ID: RPRK220221152327 Ramp Type: Type 1 - Perpendicular Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 2

Codes/Mitigation Info/Possible Solution **Field Measurements/Component Compliance**



Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

OC Std/PROW:
R304.5.3, STD 1115

Total Cost: \$ **3080**

Parcel ID Number **682-022-24**

Ramp Island Or Median **None**

Ramp Orientation **NonDiag**

Google Street View Link:
http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.46137956,-117.69405966

Street 1 Name: STREET_OF_THE_GOLDEN_LANTERN

Stop Condition-Street 1 **NoControl**

Street 2 Name: STREET_OF_THE_GOLDEN_LANTERN

Stop Condition-Street 2 **N/A**

| Compliance | Description | Data | Compliance | Description | Data |
|------------|----------------------------------------------|------|------------|-------------------------------|------|
| N/A | Ramp Length (in) | 62 | N/A | Flare Type LT | |
| Yes | Ramp Width (in) | 64 | | | N/A |
| Yes | Ramp Run Slope (%) | 5.9 | N/A | Flare Slope LT (%) | N/A |
| No | Ramp Cross Slope (%) | 2.4 | N/A | Flare Traversable LT | N/A |
| N/A | Landing Present | N/A | N/A | Flare Type RT | |
| N/A | Landing Length (in) | N/A | | | N/A |
| N/A | Landing Width (in) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Landing Run Slope (%) | N/A | N/A | Flare Traversable RT | N/A |
| N/A | Landing Cross Slope (%) | N/A | N/A | DWS Provided | N/A |
| N/A | Landing Movement Obstructed? | N/A | N/A | DWS Contrast | N/A |
| | Landing Movement Type | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing Shared | N/A | N/A | DWS Full Width | N/A |
| N/A | Clear Space | N/A | N/A | DWS Offset Left (in) | N/A |
| N/A | Clear Space To Crosswalk (in) | N/A | N/A | DWS Offset Right (in) | N/A |
| N/A | Marked Crosswalk 1 | No | N/A | Marked Crosswalk 2 | N/A |
| | Crossing 1 Direction | W | | Crossing 2 Direction | N/A |
| | Marked Crosswalk 1 Width (in) | N/A | | Marked Crosswalk 2 Width (in) | N/A |
| N/A | Ramp Inside Crosswalk 1 | N/A | Yes | Ramp Inside Crosswalk 2 | N/A |
| | Crossing 1 Slope (%) | 2.3 | | Crossing 2 Slope (%) | N/A |
| | Crossing 1 Cross Slope (%) | 1.4 | | Crossing 2 Cross Slope (%) | N/A |
| N/A | Gutter Ponding | N/A | N/A | Curb Slope | 1.1 |
| Yes | Gutter Lip Height (in) | 0 | | Road Run Slope (%) | N/A |
| N/A | Gutter Run Slope (%) | N/A | | Road Cross Slope (%) | N/A |
| N/A | Gutter Cross Slope (%) | N/A | | | |
| Yes | Overall Surface Condition: Acceptable | | Yes | Perp Joint Present | Yes |
| | Cross Gutter Present? | No | | Spandrel Present? | No |
| | Replace Cross Gutter? | N/A | | Replace Spandrel? | N/A |

Obstruction and Utility Measurement/Component Compliance

| Compliance | Description | Data | Compliance | Description | Data |
|------------|------------------------|------|------------|--------------------|------|
| Yes | Obstructions Present? | No | N/A | Utilities Present? | No |
| | Obstruction Types | N/A | | Utility Types | |
| | Obstruction Dimensions | N/A | | | N/A |

