



# Access Compliance Report Public Rights-of-Way (Curb Ramps)



**Main Street: DANA\_DR** **Cross Street: DANA\_DR** **Location: S**

**ADA ID: RPRK220221163323** **Ramp Type: Type 4 - Parallel** **Initial Pass/Fail: Pass** **Overall Compliance: Yes** **Severity Score: 0**

### Codes/Mitigation Info/Possible Solution

### Field Measurements/Component Compliance



Possible Solutions:

N/A

Surveyor Notes:

N/A

OC Std/PROW:

N/A

Total Cost: \$ 0

Parcel ID Number: **682-011-28**  
 Ramp Island Or Median: **None**  
 Ramp Orientation: **NonDiag**  
 Google Street View Link:  
[http://www.google.com/maps/@?api=1&map\\_action=pano&viewpoint=33.45706819,-117.69487467](http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.45706819,-117.69487467)

Street 1 Name: **DANA\_DR**  
 Stop Condition-Street 1: **NoControl**  
 Street 2 Name: **DANA\_DR**  
 Stop Condition-Street 2: **N/A**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	97	N/A	Ramp Length RT (in)	107
Yes	Ramp Width LT (in)	66	Yes	Ramp Width RT (in)	66
Yes	Ramp Run Slope LT (%)	3.5	Yes	Ramp Run Slope RT (%)	3.6
Yes	Ramp Cross Slope LT (%)	0.4	Yes	Ramp Cross Slope RT (%)	1.4
N/A	Landing Present	Yes	Yes	DWS Provided	Yes
N/A	Landing Length (in)	66	Yes	DWS Contrast	Yes
Yes	Landing Width (in)	48	Yes	DWS Length (in)	36
Yes	Landing Run Slope (%)	1.3	Yes	DWS Full Width	Yes
Yes	Landing Cross Slope (%)	0.6		DWS Offset Type	Single
N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
	Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
N/A	Landing Shared	No			
N/A	Clear Space	N/A			
N/A	Clear Space To Crosswalk (in)	N/A			
N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	N/A
	Crossing 1 Direction	S		Crossing 2 Direction	N/A
	Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
	Crossing 1 Slope (%)	0.5		Crossing 2 Slope (%)	N/A
	Crossing 1 Cross Slope (%)	0.5		Crossing 2 Cross Slope (%)	N/A
Yes	Gutter Ponding	No	Yes	Curb Slope	1.3
Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
Yes	Gutter Run Slope (%)	1.6		Road Cross Slope (%)	N/A
Yes	Gutter Cross Slope (%)	0.4	Yes	Perpendicular Joint Present	Yes
Yes	Overall Surface Condition	Acceptable			
	Cross Gutter Present?	No		Spandrel Present?	No
	Replace Cross Gutter?	N/A		Replace Spandrel?	N/A

### Obstruction and Utility Measurement/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A			N/A

