

B 1 Addl APS Features Notes

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: KELLOGG_DR Cross Street: MOUNTAIN_VIEW_AVE Location: N

Walli Street. RELLOGG_DR			C1055 31	ieet. WOONTAIN_VIEW_AVE		Location.	14
ADA ID: SGAT210922124131	Signal Typ	e:One Push Button-Non APS	Overall (Compliance: No Severity Scores	В	TN 1: 10 BTN 2: N/A No BTN:	: N/A
Codes	/Mitigation	Info/Possible Solution		Field Measurem	ents/0	Component Compliance	
				Compliance Description	Data	Compliance Description	Data
Possible Solutions: Replace Sign Button With APS Button.			nal Push	Button Count Bu	ıtton1	Yes Distant to Additional Button (in)	300
	Zulion minima o zulioni		Additional Button Present?	Yes	N/A Additional Button ID SGAT210922	2123909	
and the second	7 / //			Located In An Island/Median?	No		
				N/A B 1 Sign Present?	Yes	N/A B 2 Sign Present?	N/A
	Surveyor Notes: N/A		Yes B 1 Sign Purpose?	Yes	N/A B 2 Sign Purpose?	N/A	
	Surveyor Notes. N/A		Yes B 1 Sign Lettering & Contrast?	Yes	N/A B 2 Sign Lettering & Contrast?	N/A	
			Yes B 1 Parallel To XWalk?	Yes	N/A B 2 Parallel To XWalk?	N/A	
TOUR E			N/A B 1 PAR to Button?	N/A	N/A B 2 PAR to Button?	N/A	
El Maria	OC Std/PROW: MUTCD 4e.08		N/A B 1 PAR to XWalk?	N/A	N/A B 2 PAR to XWalk?	N/A	
	OC Star ROW. MIG 10D 46.00		Yes B 1 Clear Floor Space?	Yes	N/A B 2 Clear Floor Space?	N/A	
A 100 100 100 100 100 100 100 100 100 10	/ of			N/A B 1 FWD Approach?	N/A	N/A B 2 FWD Approach?	N/A
	37			N/A B 1 FWD Approach Constrained?	N/A	N/A B 2 FWD Approach Constrained?	N/A
		Total Cost: \$	900	N/A B 1 FWD Approach Reach (in)	N/A	N/A B 2 FWD Approach Reach (in)	N/A
	AK.V	Total Cost.		N/A B 1 FWD Approach Width (in)		N/A B 2 FWD Approach Width (in)	N/A
				N/A B 1 FWD Approach Obstruction?	N/A	N/A B 2 FWD Approach Obstruction?	N/A
				N/A B 1 FWD Approach Obstruction Dist (in)	N/A	N/A B 2 FWD Approach ObstructionDist (ii	n) N/A
				N/A B 1 PARA Approach?	N/A	N/A B 2 PARA Approach?	N/A
APS Compliance				N/A B 1 PARA Approach Constrained?	No	N/A B 2 PARA Approach Constrained?	N/A
				Yes B 1 PARA Approach Reach (in)	0	N/A B 2 PARA Approach Reach (in)	N/A
				N/A B 1 PARA Approach Width (in)		N/A B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	No	N/A B 2 PARA Approach Obstruction?	N/A
				N/A B 1 PARA Approach Obstruction Dist (in)	N/A	N/A B 2 PARA Approach Obstruction Dist	(in) N/A
N/A Is Button 1 APS or Non-APS?	NonAPS		N/A	Yes B 1 Clear Floor Space Slope (%)	0.8	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	2	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	2.4	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	42	N/A B 2 Height (in)	N/A
No B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2.25	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	SE	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	40	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	23	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number 348-0	12-38		
D 1 Addl ADC Footures Notes		D.O. Addl ADC Factures Notes		Coords Street View Link			

N/A

Google Street View Link

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.88044927,-117.80004355

B 2 Addl APS Features Notes

N/A