

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: E CHAPMAN AVE **Cross Street: S ESPLANADE ST** Location:

ADA ID: SGAT210927135419 Signal Type: One Push Button-Non APS **Overall Compliance: No Severity Scores:** BTN 1: 35 BTN 2: N/A No BTN: N/A

Codes/Mitigation	ation Info/	Possible :	Solution
------------------	-------------	------------	----------

Field Measurements/Component Compliance



Possible Solutions: Replace Signal Push **Button With APS Button. Remove & Relocate** Sign.

Surveyor Notes: N/A

OC Std/PROW: MUTCD 4e.08, R404.2, R404.3

650





Fleid Measurements/Component Compliance								
Con	npliance	Description	Data	Comp	oliance	Description	D	ata
	Button C	ount	Button1	Yes	Distant t	to Additional Bu	tton (in)	200
	Additiona	al Button Present?	Yes	N/A	Addition	al Button ID	SGAT21092713	5235
	Located	In An Island/Median?	No					
N/A	B 1 Sign	Present?	Yes	N/A	B 2 Sigr	Present?		N/A
Yes	B 1 Sign	Purpose?	Yes	N/A	B 2 Sigr	Purpose?		N/A
Yes	B 1 Sign	Lettering & Contrast?	Yes	N/A	B 2 Sigr	Lettering & Co	ontrast?	N/A
Yes	B 1 Para	illel To XWalk?	Yes	N/A	B 2 Para	allel To XWalk?		N/A
N/A	B 1 PAR	to Button?	N/A	N/A	B 2 PAR	to Button?		N/A
N/A	B 1 PAR	to XWalk?	N/A	N/A	B 2 PAR	to XWalk?		N/A
Yes	B 1 Clea	r Floor Space?	Yes	N/A	B 2 Clea	ar Floor Space?	•	N/A
N/A	B 1 FWD	Approach?	N/A	N/A	B 2 FWD	O Approach?		N/A
N/A	B 1 FWD	Approach Constrained?	N/A	N/A	B 2 FWD	Approach Cor	nstrained?	N/A
N/A	B 1 FWD	Approach Reach (in)	N/A	N/A	B 2 FWI	O Approach Rea	ach (in)	N/A
N/A	B 1 FWD	Approach Width (in)	N/A	N/A	B 2 FWI	O Approach Wid	dth (in)	N/A
N/A	B 1 FWD	Approach Obstruction?	N/A	N/A	B 2 FWI	O Approach Ob	struction?	N/A
N/A	B 1 FWD	Approach Obstruction Dist (in) N/A	N/A	B 2 FWI	O Approach Ob	structionDist (in)	N/A
N/A	B 1 PAR	A Approach?	N/A	N/A	B 2 PAR	A Approach?		N/A
N/A	B 1 PAR	A Approach Constrained?	No	N/A	B 2 PAR	RA Approach Co	nstrained?	N/A
Yes	B 1 PAR	A Approach Reach (in)	0	N/A	B 2 PAR	RA Approach Re	each (in)	N/A
N/A	B 1 PAR	A Approach Width (in)	N/A	N/A	B 2 PAR	RA Approach Wi	dth (in)	N/A
N/A	B 1 PAR	A Approach Obstruction?	No	N/A	B 2 PAR	A Approach Ob	struction?	N/A
N/A	B 1 PAR	A Approach Obstruction Dist	(in) N/A	N/A	B 2 PAR	A Approach Ob	struction Dist (in)	N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78788604,-117.80977657



APS Compliance

Ar 3 compliance			• • • • • • • • • • • • • • • • • • • •	` '	1 '	` '	
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	2.4	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%	2.4	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.5	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	39	N/A B 2 Height (in)	N/A
No B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2.25	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	s	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	No B 1 DistanceTo XWalk (in)	73	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	29	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number	383-261-12		
B 1 Addl APS Features Notes		B 2 Addl APS Features Notes		Google Street View Link			

N/A