

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A N/A

Main Street: N_GLASSELL_ST Cross Street: FRONTERA_ST Location: NE

ADA ID: SGAT220127092228 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Scores: BTN 1: 60 BTN 2: N/A No BTN: N/A

Compliance Description

Additional Button Present?

Yes B 1 Sign Lettering & Contrast?
Yes B 1 Parallel To XWalk?

N/A B 1 FWD Approach Constrained?

No B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

N/A B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

N/A B 1 PARA Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

N/A B 1 PAR to Button?


N/A B 1 PAR to XWalk?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

No B 1 Clear Floor Space?

Codes/Mitigation Info/Possible Solution



Compliance Description

N/A Additional Button ID

N/A B 2 Sign Present?

N/A B 2 Sign Purpose?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

N/A B 2 FWD Approach?

N/A B 2 PARA Approach?

N/A B 2 Parallel To XWalk?

N/A B 2 Clear Floor Space?

N/A Distant to Additional Button (in)

N/A B 2 Sign Lettering & Contrast?

N/A B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Reach (in)

N/A B 2 FWD Approach Width (in)

N/A B 2 FWD Approach Obstruction?

N/A B 2 PARA Approach Constrained?

N/A B 2 PARA Approach Reach (in)

N/A B 2 PARA Approach Width (in)

N/A B 2 PARA Approach Obstruction?

N/A B 2 FWD Approach ObstructionDist (in)

Data

Button1

No

Yes

N/A

No

N/A

N/A



Possible Solutions: Replace Signal Push Button With APS Button. Provide PAR As Indicated. Provide Clear Space.

Surveyor Notes: N/A

OC Std/PROW: R404.3, R404.1, R404.7.1, R406.2, R403.4, DMS-11132, R104.2, R209.1, MUTCD 4e.08

Total Cost:

1656







APS Compliance				N/A B 1 PARA Approach Obstruction Dis	t (in) N/A	N/A B 2 PARA Approach Obstruction Dist (i	ın) N/A
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	N/A	N/A B 1 Clear Floor Space Slope (%)	N/A	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	N/A B 1 Clear Floor Space XSlope (%)	N/A	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	N/A	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	48	N/A B 2 Height (in)	N/A
No B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	No B 1 Pressure (#)	10	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	No B 1 Closed Fist Operation?	No	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	No B 1 Diameter (in)	0.25	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	s	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	0	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	36	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number 3	360-061-13		
B 1 Addl APS Features Notes	N/A	B 2 Addl APS Features Notes	N/A	Google Street View Link http://www.google.com/maps/@?api=1&map-action=pano&viewpoint=33.84643829,-117.85436799			