

B 1 Addl APS Features Notes

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: CHAPMAN_AVE Cross Street: CHAPMAN_AVE Location: SW

Maill Street. Charman_ave		C1055 3tl	TEEL. CHAPINIAN_AVE		Location.	344	
ADA ID: SGAT220201095756	Signal Typ	e:N/A	Overall C	compliance: Yes Severity Sco	res: B	TN 1: N/A BTN 2: N/A No BTN	:
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance							
	Possible Solutions: N/A		Compliance Description	Data	Compliance Description	Data	
	Possible Solutions: N/A		Button Count		N/A Distant to Additional Button (in)	240	
(0)		1 6		Additional Button Present?	Yes	N/A Additional Button ID SGAT22020	1095310
GHAPMANLAVE				Located In An Island/Median?	No		
20 20 20 20 20	Surveyor Notes: Under construction at the time of collection		N/A B 1 Sign Present?	N/A	N/A B 2 Sign Present?	N/A	
e Anti-			N/A B 1 Sign Purpose?	N/A	N/A B 2 Sign Purpose?	N/A	
The state of the s			N/A B 1 Sign Lettering & Contrast?	N/A	N/A B 2 Sign Lettering & Contrast?	N/A	
- Marie 18 18 18 18 18 18 18 18 18 18 18 18 18			N/A B 1 Parallel To XWalk?	N/A	N/A B 2 Parallel To XWalk?	N/A	
	OC Std/PROW: N/A		N/A B 1 PAR to Button?	N/A	N/A B 2 PAR to Button?	N/A	
			N/A B 1 PAR to XWalk?	N/A	N/A B 2 PAR to XWalk?	N/A	
			N/A B 1 Clear Floor Space?	N/A	N/A B 2 Clear Floor Space?	N/A	
				N/A B 1 FWD Approach?	N/A	N/A B 2 FWD Approach?	N/A
				N/A B 1 FWD Approach Constrained?	N/A	N/A B 2 FWD Approach Constrained?	N/A
	6	Total Cost: \$	0	N/A B 1 FWD Approach Reach (in)	N/A		N/A
				N/A B 1 FWD Approach Width (in)	N/A	N/A B 2 FWD Approach Width (in)	N/A
				N/A B 1 FWD Approach Obstruction?	N/A	N/A B 2 FWD Approach Obstruction?	N/A
				N/A B 1 FWD Approach Obstruction Dis	t (in) N/A	N/A B 2 FWD Approach ObstructionDist (i	in) N/A
				N/A B 1 PARA Approach?	N/A	N/A B 2 PARA Approach?	N/A
				N/A B 1 PARA Approach Constrained?	N/A	N/A B 2 PARA Approach Constrained?	N/A
				N/A B 1 PARA Approach Reach (in)	N/A	N/A B 2 PARA Approach Reach (in)	N/A
				N/A B 1 PARA Approach Width (in)	N/A	N/A B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	N/A	N/A B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction Dis	st (in) N/A	N/A B 2 PARA Approach Obstruction Dist	(in) N/A
N/A Is Button 1 APS or Non-APS?	N/A	N/A Is Button 2 APS or Non-APS?	N/A	N/A B 1 Clear Floor Space Slope (%)	N/A	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	N/A B 1 Clear Floor Space XSlope (%)	N/A	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	N/A	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	N/A B 1 Height (in)	N/A	N/A B 2 Height (in)	N/A
N/A B 1 Pilot Light?	N/A	N/A B 2 Pilot Light?	N/A	N/A B 1 Pressure (#)	N/A	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	N/A B 1 Closed Fist Operation?	N/A	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	N/A B 1 Diameter (in)	N/A	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	N/A	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	N/A B 1 DistanceTo XWalk (in)	N/A	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	N/A B 1 DistanceTo Curb (in)	N/A	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	N/A	B 2 Addl APS Features?	N/A	Parcel Identification Number	131-401-09		

N/A

Google Street View Link

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78821144,-117.99315405

B 2 Addl APS Features Notes

N/A