

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

N/A

N/A

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

**Cross Street: OSO PKWY** Main Street: N/A Location:

ADA ID: SGAT220208114440 Signal Type: One Push Button-Non APS BTN 1: 35 BTN 2: N/A No BTN: N/A **Overall Compliance: No Severity Scores:** 

Compliance Description

Additional Button Present?

Yes B 1 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk?

N/A B 1 FWD Approach Constrained?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

**N/A** B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

N/A B 1 PARA Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

N/A B 1 PAR to Button?

N/A B 1 PAR to XWalk?

Yes B 1 Clear Floor Space?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Compliance Description

N/A Additional Button ID

N/A B 2 Sign Present?

N/A B 2 Sign Purpose?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

N/A B 2 Parallel To XWalk?

N/A B 2 Clear Floor Space? N/A B 2 FWD Approach?

N/A B 2 PARA Approach?

N/A Distant to Additional Button (in)

N/A B 2 Sign Lettering & Contrast?

N/A B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Obstruction?

N/A B 2 PARA Approach Constrained? N/A B 2 PARA Approach Reach (in)

N/A B 2 PARA Approach Width (in)

No N/A B 2 PARA Approach Obstruction?

N/A B 2 FWD Approach ObstructionDist (in)

N/A B 2 FWD Approach Reach (in)

N/A B 2 FWD Approach Width (in)

Data

Button1

No

Yes

N/A

Yes

N/A

No



Possible Solutions: Replace Signal Push **Button With APS Button. Remove & Relocate** Sign.

Surveyor Notes: N/A

OC Std/PROW: MUTCD 4e.08, R404.2, R404.3

Total Cost:

650







APS Compliance				N/A B 1 PARA Approach Obstruction Dis	st (in) N/A	N/A B 2 PARA Approach Obstruction Dist (	(in) <b>N/A</b>
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	5.6	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	6.9	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	4	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	39	N/A B 2 Height (in)	N/A
No B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	E	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	No B 1 DistanceTo XWalk (in)	82	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	28	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number	125-099-18		
B 1 Addl APS Features Notes		B 2 Addl APS Features Notes		Google Street View Link			
	N/A		N/A	http://www.google.com/maps/@?api=1↦_action=pano&viewpoint=33.58572764,-117.61330798			