

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



N/A

N/A

N/A

N/A

N/A

Main Street: ANTONIO_PKWY Cross Street: N/A Location: W

ADA ID: SGAT220208124317 Signal Type:One Push Button-APS Overall Compliance: No Severity Scores: BTN 1: 25 BTN 2: N/A No BTN: N/A

	Codes/Mitigation Info
(7 5 %)	
	A 10 B
Alley (
S	ONORTH HE
	ON GILLIA
4	
	The second secon

Mitigation Info/Possible Solution

Possible Solutions: Remove and Replace Clear Space.

Surveyor Notes: N/A

OC Std/PROW: R404.2, R404.3

Total Cost:

iotal cost.







378

N/A N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes B 1 Closed Fist Operation?

Yes B 1 Diameter (in)

N/A B 1 Crossing Direction

Yes B 1 DistanceTo XWalk (in)

Parcel Identification Number

Google Street View Link

Yes B 1 DistanceTo Curb (in)

APS	Comp	liance
-----	------	--------

		AF 3 COIII	pliance
N/A	Is Button 1 APS or Non-APS?	APS	N/A Is Button 2 APS or Non-APS?
N/A	B 1 VibroTact Arrow?	Yes	N/A B 2 VibroTact Arrow?
Yes	B 1 VibroTact Parallel to Xing?	Yes	N/A B 2 VibroTact Parallel to Xing?
N/A	B 1 VibroTact Contrast	Yes	N/A B 2 VibroTact Contrast
Yes	B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?
Yes	B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?
N/A	B 1 Walk Indicator Type	VerbalMessage	N/A B 2 Walk Indicator Type
N/A	B 1 Walk Indicator Audible?	Yes	N/A B 2 Walk Indicator Audible?
N/A	B 1 Locator Tone?	Yes	N/A B 2 Locator Tone?
N/A	B 1 Tone Audible Range?	Yes	N/A B 2 Tone Audible Range?
	B 1 Addl APS Features?	No	B 2 Addl APS Features?
	B 1 Addl APS Features Notes		B 2 Addl APS Features Notes
		N/A	

Field Measurements/Component Compliance						
Compliance Description Da	ata	Compliance Description Da	ata			
Button Count Butt	on1	Yes Distant to Additional Button (in)	344			
Additional Button Present?	Yes	N/A Additional Button ID SGAT220208124	1419			
Located In An Island/Median?	No					
N/A B 1 Sign Present?	Yes	N/A B 2 Sign Present?	N/A			
Yes B 1 Sign Purpose?	Yes	N/A B 2 Sign Purpose?	N/A			
Yes B 1 Sign Lettering & Contrast?	Yes	N/A B 2 Sign Lettering & Contrast?	N/A			
Yes B 1 Parallel To XWalk?	Yes	N/A B 2 Parallel To XWalk?	N/A			
N/A B 1 PAR to Button?	N/A	N/A B 2 PAR to Button?	N/A			
N/A B 1 PAR to XWalk?	N/A	N/A B 2 PAR to XWalk?	N/A			
Yes B 1 Clear Floor Space?	Yes	N/A B 2 Clear Floor Space?	N/A			
N/A B 1 FWD Approach?	N/A	N/A B 2 FWD Approach?	N/A			
N/A B 1 FWD Approach Constrained?	N/A	N/A B 2 FWD Approach Constrained?	N/A			
N/A B 1 FWD Approach Reach (in)	N/A	N/A B 2 FWD Approach Reach (in)	N/A			
N/A B 1 FWD Approach Width (in)	N/A	N/A B 2 FWD Approach Width (in)	N/A			
N/A B 1 FWD Approach Obstruction?	N/A	N/A B 2 FWD Approach Obstruction?	N/A			
N/A B 1 FWD Approach Obstruction Dist (in)	N/A	N/A B 2 FWD Approach ObstructionDist (in)	N/A			
N/A B 1 PARA Approach?	N/A	N/A B 2 PARA Approach?	N/A			
N/A B 1 PARA Approach Constrained?	No	N/A B 2 PARA Approach Constrained?	N/A			
Yes B 1 PARA Approach Reach (in)	0	N/A B 2 PARA Approach Reach (in)	N/A			
N/A B 1 PARA Approach Width (in)	N/A	N/A B 2 PARA Approach Width (in)	N/A			
N/A B 1 PARA Approach Obstruction?	No	N/A B 2 PARA Approach Obstruction?	N/A			
N/A B 1 PARA Approach Obstruction Dist (in)	N/A	N/A B 2 PARA Approach Obstruction Dist (in)	N/A			
No B 1 Clear Floor Space Slope (%)	2.94	N/A B 2 Clear Floor Space Slope (%)	N/A			
Yes B 1 Clear Floor Space XSlope (%)	1	N/A B 2 Clear Floor Space XSlope (%)	N/A			
N/A B 1 PAR Slope (%)	1	N/A B 2 PAR Slope (%)	N/A			
Yes B 1 Height (in)	39	N/A B 2 Height (in)	N/A			
Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A			

Yes N/A B 2 Closed Fist Operation?

36 N/A B 2 DistanceTo XWalk (in)

38 N/A B 2 DistanceTo Curb (in)

2 N/A B 2 Diameter (in)

787-251-16

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.59095844,-117.62713306

SE N/A B 2 Crossing Direction