


Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: HAZARD AVE **Cross Street: NEWLAND ST** Location:

ADA ID: SGRK210929120805 Signal Type: One Push Button-Non APS **Overall Compliance: No Severity Scores:** BTN 1: 10 BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution





Possible Solutions: Replace Signal Push **Button With APS Button.** Surveyor Notes: N/A OC Std/PROW: MUTCD 4e.08

900 Total Cost:





Compliance Description	Data	Compliance Description D	ata
Button Count	Button1	Yes Distant to Additional Button (in)	282
Additional Button Present?	Yes	N/A Additional Button ID SGRK21092912	0604
Located In An Island/Median?	No		
N/A B 1 Sign Present?	Yes	N/A B 2 Sign Present?	N/A
Yes B 1 Sign Purpose?	Yes	N/A B 2 Sign Purpose?	N/A
Yes B 1 Sign Lettering & Contrast?	Yes	N/A B 2 Sign Lettering & Contrast?	N/A
Yes B 1 Parallel To XWalk?	Yes	N/A B 2 Parallel To XWalk?	N/A
N/A B 1 PAR to Button?	N/A	N/A B 2 PAR to Button?	N/A
N/A B 1 PAR to XWalk?	N/A	N/A B 2 PAR to XWalk?	N/A
Yes B 1 Clear Floor Space?	Yes	N/A B 2 Clear Floor Space?	N/A
N/A B 1 FWD Approach?	N/A	N/A B 2 FWD Approach?	N/A
N/A B 1 FWD Approach Constrained?	N/A	N/A B 2 FWD Approach Constrained?	N/A
N/A B 1 FWD Approach Reach (in)	N/A	N/A B 2 FWD Approach Reach (in)	N/A
N/A B 1 FWD Approach Width (in)	N/A	N/A B 2 FWD Approach Width (in)	N/A
N/A B 1 FWD Approach Obstruction?	N/A	N/A B 2 FWD Approach Obstruction?	N/A
N/A B 1 FWD Approach Obstruction Dist	(in) N/A	N/A B 2 FWD Approach ObstructionDist (in)	N/A
N/A B 1 PARA Approach?	N/A	N/A B 2 PARA Approach?	N/A
N/A B 1 PARA Approach Constrained?	No	N/A B 2 PARA Approach Constrained?	N/A
Yes B 1 PARA Approach Reach (in)	0	N/A B 2 PARA Approach Reach (in)	N/A
N/A B 1 PARA Approach Width (in)	N/A	N/A B 2 PARA Approach Width (in)	N/A
N/A B 1 PARA Approach Obstruction?	No	N/A B 2 PARA Approach Obstruction?	N/A
N/A B 1 PARA Approach Obstruction Dist	(in) N/A	N/A B 2 PARA Approach Obstruction Dist (in)	N/A
Yes B 1 Clear Floor Space Slope (%)	1.3	N/A B 2 Clear Floor Space Slope (%)	N/A
Yes B 1 Clear Floor Space XSlope (%)	2	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 PAR Slope (%)	5.3	N/A B 2 PAR Slope (%)	N/A
Yes B 1 Height (in)	48	N/A B 2 Height (in)	N/A
Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A

APS Compliance			N/A B 1 PARA Approach Obstruction Dist (in) N/A N/A B 2 PARA Approach Obstruction Dist (in) N/A				
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	1.3	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	Yes B 1 Clear Floor Space XSlope (%)	2	N/A B 2 Clear Floor Space XSlope (%)	N/A
N/A B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	5.3	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	48	N/A B 2 Height (in)	N/A
No B 1 Pilot Light?	No	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	N/A	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	s	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	37	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	20	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number 09	7-183-12		
B 1 Addl APS Features Notes	N/A	B 2 Addl APS Features Notes	N/A	Google Street View Link http://www.google.com/maps/@?api=1↦_a	ction=pano8	viewpoint=33.75216026,-117.98118231	