

B 1 Addl APS Features Notes

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: BOLSA_AVE Cross Street: BEACH_BLVD Location: SE

ADA ID: SGRK210929150816 Signal Type:One Push Button-APS Overall Compliance: No Severity Scores: BTN 1: 25 BTN 2: N/A No BTN: N/A							
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance							
		Possible Solutions: Replace Signal Push Button With APS Button. Remove & Relocate		Compliance Description	Data	Compliance Description	Data
TE THE PRODUCTION OF THE PARTY	T. C. C.			Button Count E	Button1	Yes Distant to Additional Button (in)	185
	Complete Com	Sign.		Additional Button Present?	Yes	N/A Additional Button ID SGRK21092	9151121
BOLSA_AVE		C-2		Located In An Island/Median?	No		
				N/A B 1 Sign Present?	Yes	N/A B 2 Sign Present?	N/A
9		Surveyor Notes: N/A		Yes B 1 Sign Purpose?	Yes	N/A B 2 Sign Purpose?	N/A
en e e e e e e e e e e e e e e e e e e				Yes B 1 Sign Lettering & Contrast?	Yes	N/A B 2 Sign Lettering & Contrast?	N/A
	CARLET .			Yes B 1 Parallel To XWalk?	Yes	N/A B 2 Parallel To XWalk?	N/A
		OC Std/PROW: MUTCD 4e.08, R404.2		N/A B 1 PAR to Button?	N/A	N/A B 2 PAR to Button?	N/A
C VIII				N/A B 1 PAR to XWalk?	N/A	N/A B 2 PAR to XWalk?	N/A
		3		Yes B 1 Clear Floor Space?	Yes	N/A B 2 Clear Floor Space?	N/A
				N/A B 1 FWD Approach?	N/A	N/A B 2 FWD Approach?	N/A
			650	N/A B 1 FWD Approach Constrained?	N/A	N/A B 2 FWD Approach Constrained?	N/A
		Total Cost: \$		N/A B 1 FWD Approach Reach (in)	N/A	N/A B 2 FWD Approach Reach (in)	N/A
Iotal Cost.				N/A B 1 FWD Approach Width (in)	N/A	N/A B 2 FWD Approach Width (in)	N/A
18695 E			N/A B 1 FWD Approach Obstruction?	N/A	N/A B 2 FWD Approach Obstruction?	N/A	
				N/A B 1 FWD Approach Obstruction Dist (in	N/A	N/A B 2 FWD Approach ObstructionDist (i	in) N/A
				N/A B 1 PARA Approach?	N/A	N/A B 2 PARA Approach?	N/A
				N/A B 1 PARA Approach Constrained?	No	N/A B 2 PARA Approach Constrained?	N/A
				Yes B 1 PARA Approach Reach (in)	0	N/A B 2 PARA Approach Reach (in)	N/A
				N/A B 1 PARA Approach Width (in)	N/A	N/A B 2 PARA Approach Width (in)	N/A
				N/A B 1 PARA Approach Obstruction?	No	N/A B 2 PARA Approach Obstruction?	N/A
APS Compliance				N/A B 1 PARA Approach Obstruction Dist (in	n) N/A	N/A B 2 PARA Approach Obstruction Dist	(in) N/A
N/A Is Button 1 APS or Non-APS?	APS		N/A	Yes B 1 Clear Floor Space Slope (%)	2.9	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	Yes	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	8.4	N/A B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	Yes	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	4	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	Yes	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	40	N/A B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	VerbalMessage	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	Yes	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	N	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	No	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	0	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	No B 1 DistanceTo Curb (in)	81	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	Yes	B 2 Addl APS Features?	N/A	` ,	-153-10	•	

N/A

Google Street View Link

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.74455725,-117.98923955

B 2 Addl APS Features Notes

N/A