

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

SGRK210930105426

283

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: BOLSA_AVE Cross Street: VAN_BUREN_ST Location: SE

ADA ID: SGRK210930105150 Signal Type:One Push Button-Non APS Overall Compliance: No Severity Scores: BTN 1: 25 BTN 2: N/A No BTN: N/A

Compliance Description

Additional Button Present?

Yes B 1 Sign Lettering & Contrast?
Yes B 1 Parallel To XWalk?

N/A B 1 FWD Approach Constrained?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

N/A B 1 PARA Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

N/A B 1 PAR to Button?

N/A B 1 PAR to XWalk?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

Yes B 1 Clear Floor Space?

Codes/Miti	gation Info/P	ossible :	Solution
------------	---------------	-----------	----------

Field Measurements/Component Compliance

Compliance Description

N/A Additional Button ID

N/A B 2 Sign Present?

N/A B 2 Sign Purpose?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

N/A B 2 FWD Approach?

N/A B 2 PARA Approach?

N/A B 2 Parallel To XWalk?

N/A B 2 Clear Floor Space?

Yes Distant to Additional Button (in)

N/A B 2 Sign Lettering & Contrast?

N/A B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Reach (in)

N/A B 2 FWD Approach Width (in)

N/A B 2 FWD Approach Obstruction?

N/A B 2 PARA Approach Constrained?N/A B 2 PARA Approach Reach (in)

N/A B 2 PARA Approach Width (in)

N/A B 2 PARA Approach Obstruction?

N/A B 2 FWD Approach ObstructionDist (in)

Data

Button1

No

Yes

N/A

N/A

No

	000	cs/mitigation ini
70		
B	BOLSA_AVE	(0)B
g 3 3	30 £	THE PERSON
		-
Toron III		1/ / 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/ 1/
	3	
Dan man	WW BUREN ST	
- Ideah	N N	
FREE		
	7	
Till the	3	
Title Control of Control	CONTRACTOR	1000 CALLED TO THE TOTAL TO TH

Possible Solutions: Remove and Replace Clear Space.

Surveyor Notes: N/A

OC Std/PROW: R404.2

Total Cost:

378







APS Compliance		N/A B 1 PARA Approach Obstruction Dist	(in) N/A	N/A B 2 PARA Approach Obstruction Dist (in	1) N/A		
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	N/A	Yes B 1 Clear Floor Space Slope (%)	0.3	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	10.7	N/A B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	4.8	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	40	N/A B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
N/A B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	w	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	0	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	35	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number 10	7-191-05		
B 1 Addl APS Features Notes	N/A	B 2 Addl APS Features Notes	N/A	Google Street View Link http://www.google.com/maps/@?api=1↦_a	ction=pano8	viewpoint=33.74450269,-117.98627245	