

## **Access Compliance Report Public Rights-of-Way** (Pedestrian Signals)



Data

SGRK211007144700

190

N/A N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: HOLT AVE **Cross Street: 17TH ST** Location:

ADA ID: SGRK211007144549 Signal Type: One Push Button-APS BTN 1: 25 BTN 2: N/A No BTN: N/A **Overall Compliance: No Severity Scores:** 

Compliance Description

Additional Button Present?

Yes B 1 Sign Lettering & Contrast? Yes B 1 Parallel To XWalk?

N/A B 1 FWD Approach Constrained?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

**N/A** B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

N/A B 1 PARA Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

**Button Count** 

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

N/A B 1 PAR to Button?

N/A B 1 PAR to XWalk?

Yes B 1 Clear Floor Space?

N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

Codes/Miti	gation Info/P	ossible :	Solution
------------	---------------	-----------	----------



Compliance Description

N/A Additional Button ID

N/A B 2 Sign Present?

N/A B 2 Sign Purpose?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

N/A B 2 Parallel To XWalk?

N/A B 2 Clear Floor Space? N/A B 2 FWD Approach?

N/A B 2 PARA Approach?

Yes Distant to Additional Button (in)

N/A B 2 Sign Lettering & Contrast?

N/A B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Reach (in)

N/A B 2 FWD Approach Width (in)

N/A B 2 FWD Approach Obstruction?

N/A B 2 PARA Approach Constrained?

N/A B 2 PARA Approach Obstruction?

N/A B 2 PARA Approach Reach (in) N/A B 2 PARA Approach Width (in)

N/A B 2 FWD Approach ObstructionDist (in)

Data

Button1

No

Yes

N/A

Yes

N/A

No



Possible Solutions: Replace Signal Push **Button With APS Button. Remove & Relocate** Sign.

Surveyor Notes: N/A

OC Std/PROW: MUTCD 4e.08, R404.2, R404.3

650 Total Cost:







APS Compliance		N/A B 1 PARA Approach Obstruction Dist	(in) <b>N/A</b>	N/A B 2 PARA Approach Obstruction Dist (	ın) <b>N/A</b>		
N/A Is Button 1 APS or Non-APS?	APS	N/A Is Button 2 APS or Non-APS?	N/A	No B 1 Clear Floor Space Slope (%)	5.4	N/A B 2 Clear Floor Space Slope (%)	N/A
N/A B 1 VibroTact Arrow?	Yes	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	2.7	N/A B 2 Clear Floor Space XSlope (%)	N/A
Yes B 1 VibroTact Parallel to Xing?	? Yes	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	0.5	N/A B 2 PAR Slope (%)	N/A
N/A B 1 VibroTact Contrast	Yes	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	39	N/A B 2 Height (in)	N/A
Yes B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?	N/A	Yes B 1 Pressure (#)	5	N/A B 2 Pressure (#)	N/A
Yes B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?	N/A	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	N/A
N/A B 1 Walk Indicator Type	VerbalMessage	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	N/A
N/A B 1 Walk Indicator Audible?	Yes	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	w	N/A B 2 Crossing Direction	N/A
N/A B 1 Locator Tone?	Yes	N/A B 2 Locator Tone?	N/A	No B 1 DistanceTo XWalk (in)	64	N/A B 2 DistanceTo XWalk (in)	N/A
N/A B 1 Tone Audible Range?	Yes	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	34	N/A B 2 DistanceTo Curb (in)	N/A
B 1 Addl APS Features?	No	B 2 Addl APS Features?	N/A	Parcel Identification Number 39	95-124-05		
B 1 Addl APS Features Notes	N/A	B 2 Addl APS Features Notes	N/A	Google Street View Link http://www.google.com/maps/@?api=1↦_a	ction=pano&	viewpoint=33.76013782,-117.81389154	