



Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: COW_CAMP_RD Cross Street: CHIQUITA_CANYON_DR Location: NW

ADA ID: SGRK211124122002 Signal Type: One Push Button-Non APS Overall Compliance: No Severity Scores: BTN 1: 25 BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions: Remove and Replace Clear Space.

Surveyor Notes: Button 2 for Bike Lane

OC Std/PROW: R404.2, R404.3

Total Cost: \$ 378



APS Compliance

N/A	Is Button 1 APS or Non-APS?	NonAPS	N/A	Is Button 2 APS or Non-APS?	NonAPS
N/A	B 1 VibroTact Arrow?	N/A	N/A	B 2 VibroTact Arrow?	N/A
Yes	B 1 VibroTact Parallel to Xing?	N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A
N/A	B 1 VibroTact Contrast	N/A	N/A	B 2 VibroTact Contrast	N/A
Yes	B 1 Pilot Light?	Yes	N/A	B 2 Pilot Light?	Yes
N/A	B 1 Pilot Light Illumination?	Yes	N/A	B 2 Pilot Light Illumination?	Yes
N/A	B 1 Walk Indicator Type	N/A	N/A	B 2 Walk Indicator Type	N/A
N/A	B 1 Walk Indicator Audible?	N/A	N/A	B 2 Walk Indicator Audible?	N/A
N/A	B 1 Locator Tone?	N/A	N/A	B 2 Locator Tone?	N/A
N/A	B 1 Tone Audible Range?	N/A	N/A	B 2 Tone Audible Range?	N/A
	B 1 Addl APS Features?	No		B 2 Addl APS Features?	No
	B 1 Addl APS Features Notes	N/A		B 2 Addl APS Features Notes	N/A

Compliance	Description	Data	Compliance	Description	Data
	Button Count	Button1	Yes	Distant to Additional Button (in)	271
	Additional Button Present?	Yes	N/A	Additional Button ID	SGRK211124121853
	Located In An Island/Median?	No			
N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	Yes
Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	Yes
Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	Yes
Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	Yes
N/A	B 1 PAR to Button?	N/A	N/A	B 2 PAR to Button?	N/A
N/A	B 1 PAR to XWalk?	N/A	N/A	B 2 PAR to XWalk?	N/A
Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	Yes
N/A	B 1 FWD Approach?	N/A	N/A	B 2 FWD Approach?	N/A
N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?	N/A
N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
N/A	B 1 PARA Approach?	N/A	N/A	B 2 PARA Approach?	N/A
N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	No
Yes	B 1 PARA Approach Reach (in)	0	N/A	B 2 PARA Approach Reach (in)	0
N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
N/A	B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	No
N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach Obstruction Dist (in)	N/A
No	B 1 Clear Floor Space Slope (%)	4	N/A	B 2 Clear Floor Space Slope (%)	6
No	B 1 Clear Floor Space XSlope (%)	2.5	N/A	B 2 Clear Floor Space XSlope (%)	2.7
N/A	B 1 PAR Slope (%)	0.4	N/A	B 2 PAR Slope (%)	1.1
Yes	B 1 Height (in)	41	N/A	B 2 Height (in)	41
Yes	B 1 Pressure (#)	5	N/A	B 2 Pressure (#)	6
Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	Yes
Yes	B 1 Diameter (in)	2	N/A	B 2 Diameter (in)	2
N/A	B 1 Crossing Direction	E	N/A	B 2 Crossing Direction	S
Yes	B 1 DistanceTo XWalk (in)	28	N/A	B 2 DistanceTo XWalk (in)	32
Yes	B 1 DistanceTo Curb (in)	47	N/A	B 2 DistanceTo Curb (in)	43
Parcel Identification Number		755-311-05			
Google Street View Link					
		http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.52943983,-117.60596167			