



Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Main Street: DANA_POINT_HARBOR_DR Cross Street: STREET_OF_THE_GOLDEN_LANTERN Location: SW

ADA ID: SGRK220208163008 Signal Type: One Push Button-Non APS Overall Compliance: Yes Severity Scores: BTN 1: 0 BTN 2: N/A No BTN: N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions: N/A

Surveyor Notes: Button 2 for Bike Lane

OC Std/PROW: N/A

Total Cost: \$ 0



Compliance	Description	Data	Compliance	Description	Data
	Button Count	Button1	Yes	Distant to Additional Button (in)	273
	Additional Button Present?	Yes	N/A	Additional Button ID	SGRK220208162639
	Located In An Island/Median?	No			
N/A	B 1 Sign Present?	Yes	N/A	B 2 Sign Present?	Yes
Yes	B 1 Sign Purpose?	Yes	N/A	B 2 Sign Purpose?	Yes
Yes	B 1 Sign Lettering & Contrast?	Yes	N/A	B 2 Sign Lettering & Contrast?	Yes
Yes	B 1 Parallel To XWalk?	Yes	N/A	B 2 Parallel To XWalk?	Yes
N/A	B 1 PAR to Button?	N/A	N/A	B 2 PAR to Button?	N/A
N/A	B 1 PAR to XWalk?	N/A	N/A	B 2 PAR to XWalk?	N/A
Yes	B 1 Clear Floor Space?	Yes	N/A	B 2 Clear Floor Space?	Yes
N/A	B 1 FWD Approach?	N/A	N/A	B 2 FWD Approach?	N/A
N/A	B 1 FWD Approach Constrained?	N/A	N/A	B 2 FWD Approach Constrained?	N/A
N/A	B 1 FWD Approach Reach (in)	N/A	N/A	B 2 FWD Approach Reach (in)	N/A
N/A	B 1 FWD Approach Width (in)	N/A	N/A	B 2 FWD Approach Width (in)	N/A
N/A	B 1 FWD Approach Obstruction?	N/A	N/A	B 2 FWD Approach Obstruction?	N/A
N/A	B 1 FWD Approach Obstruction Dist (in)	N/A	N/A	B 2 FWD Approach ObstructionDist (in)	N/A
N/A	B 1 PARA Approach?	N/A	N/A	B 2 PARA Approach?	N/A
N/A	B 1 PARA Approach Constrained?	No	N/A	B 2 PARA Approach Constrained?	N/A
Yes	B 1 PARA Approach Reach (in)	0	N/A	B 2 PARA Approach Reach (in)	N/A
N/A	B 1 PARA Approach Width (in)	N/A	N/A	B 2 PARA Approach Width (in)	N/A
N/A	B 1 PARA Approach Obstruction?	No	N/A	B 2 PARA Approach Obstruction?	N/A
N/A	B 1 PARA Approach Obstruction Dist (in)	N/A	N/A	B 2 PARA Approach Obstruction Dist (in)	N/A
Yes	B 1 Clear Floor Space Slope (%)	0.8	N/A	B 2 Clear Floor Space Slope (%)	1.3
Yes	B 1 Clear Floor Space XSlope (%)	1.1	N/A	B 2 Clear Floor Space XSlope (%)	0.8
N/A	B 1 PAR Slope (%)	1.2	N/A	B 2 PAR Slope (%)	1.1
Yes	B 1 Height (in)	47	N/A	B 2 Height (in)	47
Yes	B 1 Pressure (#)	2	N/A	B 2 Pressure (#)	2
Yes	B 1 Closed Fist Operation?	Yes	N/A	B 2 Closed Fist Operation?	No
Yes	B 1 Diameter (in)	2	N/A	B 2 Diameter (in)	5
N/A	B 1 Crossing Direction	N	N/A	B 2 Crossing Direction	E
Yes	B 1 DistanceTo XWalk (in)	25	N/A	B 2 DistanceTo XWalk (in)	15
Yes	B 1 DistanceTo Curb (in)	27	N/A	B 2 DistanceTo Curb (in)	12

Parcel Identification Number 682-022-08

Google Street View Link

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.4624015,-117.69401306

APS Compliance

N/A	Is Button 1 APS or Non-APS?	NonAPS	N/A	Is Button 2 APS or Non-APS?	NonAPS
N/A	B 1 VibroTact Arrow?	N/A	N/A	B 2 VibroTact Arrow?	N/A
Yes	B 1 VibroTact Parallel to Xing?	N/A	N/A	B 2 VibroTact Parallel to Xing?	N/A
N/A	B 1 VibroTact Contrast	N/A	N/A	B 2 VibroTact Contrast	N/A
Yes	B 1 Pilot Light?	Yes	N/A	B 2 Pilot Light?	Yes
N/A	B 1 Pilot Light Illumination?	Yes	N/A	B 2 Pilot Light Illumination?	No
N/A	B 1 Walk Indicator Type	N/A	N/A	B 2 Walk Indicator Type	N/A
N/A	B 1 Walk Indicator Audible?	N/A	N/A	B 2 Walk Indicator Audible?	N/A
N/A	B 1 Locator Tone?	N/A	N/A	B 2 Locator Tone?	N/A
N/A	B 1 Tone Audible Range?	N/A	N/A	B 2 Tone Audible Range?	N/A
	B 1 Addl APS Features?	No		B 2 Addl APS Features?	No
	B 1 Addl APS Features Notes	N/A		B 2 Addl APS Features Notes	N/A