

Access Compliance Report Public Rights-of-Way (Pedestrian Signals)



Data

SGRK220208164604

186

Yes

Yes

No

Yes

N/A

N/A

Yes

N/A

Main Street: DANA POINT HARBOR DR Cross Street: STREET OF THE GOLDEN LANTERN

ADA ID: SGRK220208164210 Signal Type: One Push Button-Non APS BTN 1: 25 BTN 2: N/A No BTN: N/A **Overall Compliance: No Severity Scores:**

Compliance Description

Additional Button Present?

Yes B 1 Sign Lettering & Contrast?

N/A B 1 FWD Approach Constrained?

N/A B 1 FWD Approach Reach (in)

N/A B 1 FWD Approach Width (in)

N/A B 1 FWD Approach Obstruction?

N/A B 1 PARA Approach Constrained?

Yes B 1 PARA Approach Reach (in)

N/A B 1 PARA Approach Width (in)

N/A B 1 PARA Approach Obstruction?

N/A B 1 FWD Approach Obstruction Dist (in)

Located In An Island/Median?

Button Count

N/A B 1 Sign Present?

Yes B 1 Sign Purpose?

N/A B 1 PAR to Button?

N/A B 1 PAR to XWalk?


N/A B 1 FWD Approach?

N/A B 1 PARA Approach?

Yes B 1 Parallel To XWalk?

Yes B 1 Clear Floor Space?

Codes/Mitigation Info/Possible Solution



Compliance Description

N/A Additional Button ID

N/A B 2 Sign Present?

N/A B 2 Sign Purpose?

N/A B 2 PAR to Button?

N/A B 2 PAR to XWalk?

N/A B 2 FWD Approach?

N/A B 2 PARA Approach?

N/A B 2 Parallel To XWalk?

N/A B 2 Clear Floor Space?

N/A N/A B 2 FWD Approach Constrained?

N/A B 2 FWD Approach Reach (in)

N/A B 2 FWD Approach Width (in)

N/A B 2 FWD Approach Obstruction?

N/A B 2 PARA Approach Constrained?

N/A B 2 PARA Approach Reach (in)

N/A B 2 PARA Approach Width (in)

N/A B 2 PARA Approach Obstruction?

N/A B 2 FWD Approach ObstructionDist (in)

Yes Distant to Additional Button (in)

N/A B 2 Sign Lettering & Contrast?

Data

Button1

No

Yes

N/A

No



Possible Solutions: Remove and Replace Clear Space. Surveyor Notes: Button 2 for Bike Lane

OC Std/PROW: R404.2, R404.3

Total Cost:

378







APS Compliance				N/A B 1 PARA Approach Obstruction Dis	t (in) N/A	N/A B 2 PARA Approach Obstruction Dist ((in) N/A
N/A Is Button 1 APS or Non-APS?	NonAPS	N/A Is Button 2 APS or Non-APS?	NonAPS	No B 1 Clear Floor Space Slope (%)	2.9	N/A B 2 Clear Floor Space Slope (%)	1.3
N/A B 1 VibroTact Arrow?	N/A	N/A B 2 VibroTact Arrow?	N/A	No B 1 Clear Floor Space XSlope (%)	2.7	N/A B 2 Clear Floor Space XSlope (%)	0.3
Yes B 1 VibroTact Parallel to Xing?	N/A	N/A B 2 VibroTact Parallel to Xing?	N/A	N/A B 1 PAR Slope (%)	1.6	N/A B 2 PAR Slope (%)	1.1
N/A B 1 VibroTact Contrast	N/A	N/A B 2 VibroTact Contrast	N/A	Yes B 1 Height (in)	47	N/A B 2 Height (in)	47
Yes B 1 Pilot Light?	Yes	N/A B 2 Pilot Light?	Yes	Yes B 1 Pressure (#)	2	N/A B 2 Pressure (#)	2
N/A B 1 Pilot Light Illumination?	Yes	N/A B 2 Pilot Light Illumination?	Yes	Yes B 1 Closed Fist Operation?	Yes	N/A B 2 Closed Fist Operation?	No
N/A B 1 Walk Indicator Type	N/A	N/A B 2 Walk Indicator Type	N/A	Yes B 1 Diameter (in)	2	N/A B 2 Diameter (in)	2
N/A B 1 Walk Indicator Audible?	N/A	N/A B 2 Walk Indicator Audible?	N/A	N/A B 1 Crossing Direction	s	N/A B 2 Crossing Direction	w
N/A B 1 Locator Tone?	N/A	N/A B 2 Locator Tone?	N/A	Yes B 1 DistanceTo XWalk (in)	14	N/A B 2 DistanceTo XWalk (in)	25
N/A B 1 Tone Audible Range?	N/A	N/A B 2 Tone Audible Range?	N/A	Yes B 1 DistanceTo Curb (in)	18	N/A B 2 DistanceTo Curb (in)	23
B 1 Addl APS Features?	No	B 2 Addl APS Features?	No	Parcel Identification Number	82-311-04		
B 1 Addl APS Features Notes	N/A	B 2 Addl APS Features Notes	N/A	Google Street View Link http://www.google.com/maps/@?api=1↦	action=pano8	eviewpoint=33.46268833,-117.69355274	