

VERTICAL CONTROL DATA SHEET O.C.S. 1995 ADJUSTMENT



Designation: 3PP-26-89

Date Destroyed:

Date Revised:

GPS #:

OCS Index Map: Q14-14 Page/Grid: 893/B-2

City / Location: Santa Margarita

Line #/SSN: 381/0120 Established By: OCS 1989

Monument Type: Orange County Surveyor's 3 3/4"

Aluminum Disk

| NAVD88 (ft) | NGVD29 (ft) | Year Leveled |
|-------------|-------------|--------------|
| 1039.070 | 1036.719 | 1989 |
| | | |
| | | |
| | | |
| | | |



| For Reconnaisance Only! | | |
|-------------------------|---------------------|--|
| Latitude (30' +/-) | Longitude (30' +/-) | |
| 33 38 39.96 | 117 35 32.50 | |

Description:

DESCRIBED BY OCS 2003 - FOUND 3 3\4" OCS ALUMINUM BENCHMARK DISK STAMPED "3PP-26-89", SET IN THE SOUTHEASTERLY CORNER OF A 3.5 FT. BY 30 FT. CONCRETE CATCH BASIN. MONUMENT IS LOCATED IN THE SOUTHEASTERLY CORNER OF THE INTERSECTION OF SANTA MARGARITA AND BUENA SUERTE, 52.2 FT. SOUTHERLY OF THE CENTERLINE OF SANTA MARGARITA AND 240 FT. +/-FROM THE CENTERLINE OF BUENA SUERTE. MONUMENT IS SET LEVEL WITH THE SIDEWALK.

