

### Designation: 2L-25-71

Date Destroyed: 10/4/1996

Date Revised:

GPS #:

OCS Index Map: Q03-09

Page/Grid: 709/H-5

City / Location: Unin., Orange Co.

Line #/SSN: 265/0020

Established By: OCS 1971

Monument Type: Orange County Surveyor's 3 3/4"  
Aluminum Disk

NO PHOTO

NAVD88 (ft)	NGVD29 (ft)	Year Leveled
903.643	901.233	1986

For Reconnaissance Only!	
Latitude (30' +/-)	Longitude (30' +/-)

#### Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: ORIGINALLY AT THE END OF THE CURVE, AT THE TOP OF THE GRADE OF THE OLINDA DISPOSAL STATION (#20), 65 FT. SOUTH ALONG THE PROLONGATION OF THE CENTERLINE FROM THE END OF THE CURVE OF THE ROAD TO THE NORTH, 75 FT. WEST FROM THE CENTERLINE, 2.9 FT. WEST FROM A 1 INCH BY 2 INCH STAKE WITH LATHE MARKED "AL SOUTHWEST TOE OF SLOPE 123.9 FT. EAST ELEV. 1971-900.76 FT.", SET IN THE TOP OF A CONCRETE POST, 0.5 FT. ABOVE THE GROUND, 1 FT. EAST FROM A CHAIN LINK FENCE AND 3 FT. HIGHER THAN THE ROAD.

NO LOCATION MAP