

VERTICAL CONTROL DATA SHEET O.C.S. 1995 ADJUSTMENT



Designation: AP-09-99

Date Destroyed:

Date Revised: 5/13/1999

GPS #:

OCS Index Map: Q17-08 Page/Grid: 922/F-5

City / Location: Unin., Orange Co.

Line #/SSN: 731/0090 Established By: OCS 1999

Monument Type: Orange County Surveyor's 3 3/4"

Aluminum Disk

NAVD88 (ft)	NGVD29 (ft)	Year Leveled
598.314	595.971	2004
598.314	595.971	1999

A.P=0.8	103		
		1	

For Reconnaisance Only!			
Latitude (30' +/-)	Longitude (30' +/-)		
33 34 34.87443	117 37 57.50639		

Description:

DESCRIBED BY OCS 2003 - FOUND 3 3/4" OCS ALUMINUM BENCHMARK DISK STAMPED "AP-09-99" SET IN THE SOUTHEASTERLY CORNER OF A CONCRETE BRIDGE DECK, FLUSH WITH CONCRETE SURFACE. TO REACH THE BENCHMARK FROM THE INTERSECTION OF OSO PARKWAY AND ANTONIO PARKWAY, PROCEED SOUTHERLY 0.5 MILES ALONG ANTONIO PARKWAY TO THE SOUTHEAST CORNER OF THE BRIDGE (WILDLIFE CROSSING). MONUMENT IS LOCATED 25 FT. NORTHERLY FROM THE SOUTHERLY EDGE OF THE DECK AND 2 FT. WESTERLY FROM A CONCRETE GUARDRAIL. MONUMENT IS SET LEVEL WITH THE SIDEWALK.

