

COUNTY of ORANGE
OC PUBLIC WORKS
FIELD UNIT
FIELD DATA REPORT

DANA POINT NIGUEL SHORES - REVETMENT REPAIR - EC41908
VOLUME SUMMARY

Sub-Area	Station / Location	Surface Description		2D Area (Sq.Ft)	Cut Factor	Fill Factor	Cut (Cu. Yd.)	Fill (Cu. Yd.)	Net (Cu. Yd.)	
		Base *	Comparison**							
VOLUME INCLUDING CHANNEL & ROADS, EXCLUDING CONCRETE AREAS										
DANA POINT NIGUEL SHORES REVTMENT	10+00 TO 24+31.319	Existing conditions 2023 Surface Derived by Aerial Photogrametry	Design for Revetment Repair	376	1.0	1.0	0	677	677	Fill
TOTAL							0	677	677	<Fill>

NOTE :

OC Survey Surface Used:

*Existing Condition 22-23

**Dana Point Z3 Top Surface