

GPS #: 0025

Date Destroyed: 2/23/1999

Date Revised:

Benchmark Designation:

OCS Index Map: 6LB

Page/Grid: 992/G-4

City / Location: San Clemente

Scale Factor: 0.99995560

Ellipsoid Red. Factor: 1.00000460

Combination Factor: 0.99996023

Convergence Angle: -00 45 35.06559

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.

Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 25 55.76480	117 37 57.21220	2103666.548	6139877.663	-94.898
2007.00	33 25 55.78175	117 37 57.22762	2103668.28	6139876.38	

References: OCS SURVEY FILE # F93-43

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD PK NAIL WITH A 1 1/4" OCS BRASS TAG, STAMPED "GPS 0025", FLUSH IN ASPHALT. LOCATED SE OF THE INTER OF EL CAMINO REAL AND AVENIDA ESTACION, IN THE AREA OF THE NW CORNER OF A PARKING LOT, APPROX. 52' SOUTH OF THE CENTERLINE OF CALLE DESECHA.