

GPS #: 0088

Date Destroyed:

Date Revised: 4/13/2000

Benchmark Designation:

OCS Index Map: 5LB

Page/Grid: 831/E-6

City / Location: Unin., Orange County

Scale Factor: 0.99997684

Ellipsoid Red. Factor: 0.99997741

Combination Factor: 0.99995425

Convergence Angle: -00 48 26.32022

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.

NO PHOTO

Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 43 13.97013	117 43 08.85762	2208956.715	6114947.845	472.125
2007.00	33 43 13.98661	117 43 08.87347	2208958.40	6114946.53	

References: MONITORING SURVEYS 1997

Description:

East Hicks Canyon Dam Monitoring Station 1+00 - FD 3" OCS DISK WITH "+" DN 0.5' IN ALUMINUM WELL MONUMENT LOCATED ON TOP OF SOUTHERLY PORTION OF DAM.

