

GPS #: 0199

Date Destroyed: 11/11/1999

Date Revised:

Benchmark Designation:

OCS Index Map: 6LB

Page/Grid: 922/G-3

City / Location: Unin., Orange County

Scale Factor: 0.99996419

Ellipsoid Red. Factor: 0.99997489

Combination Factor: 0.99993908

Convergence Angle: -00 45 23.34891

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 35 28.53354	117 37 35.89044	2161530.864	6142448.802	529.592
2007.00	33 35 28.55044	117 37 35.90635	2161532.59	6142447.48	

References: OCS SURVEY FILE # 93/94-2

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD PUNCHED BOLT SPIKE AND 1 3/4" ALUMINUM WASHER STAMPED "LS 4189", FLUSH IN ASPHALT SURFACE. LOCATED 1' EAST OF THE W'LY EDGE OF PAVEMENT, AT THE BC, ALONG THE APPARENT CENTERLINE OF ANTONIO PKWY., (WITH W'LY TRAVEL L.N.S STILL UNDER CONSTRUCTION).

NO
LOCATION
MAP