

**GPS #:** **0276**

Date Destroyed:

Date Revised:

Benchmark Designation:

OCS Index Map: 6LB

Page/Grid: 862/J-5

City / Location: Unin., Orange County

Scale Factor: 0.99997219

Ellipsoid Red. Factor: 0.99992625

Combination Factor: 0.99989844

Convergence Angle: -00 44 46.07354

*Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.*



| Epoch Adjustment | Latitude       | Longitude       | Northing (ft) | Easting (ft) | Ellipsoid Height (ft) |
|------------------|----------------|-----------------|---------------|--------------|-----------------------|
| 1991.35          | 33 40 43.39415 | 117 36 28.05758 | 2193278.740   | 6148600.885  | 1541.368              |
| 2007.00          | 33 40 43.41079 | 117 36 28.07291 | 2193280.44    | 6148599.61   |                       |

References: NGS PID# DX4312, RSB 151/1-11

**Description:**

FD 3 3/4" O.C.S. ALUMINUM DISK STAMPED "6-7-3"  
SET IN 8" DIA. CONC. COLLAR UP 0.15' LOCATED  
W'LY OF LIVE OAK CANYON, IN THE O'NEILL  
REGIONAL PARK AREA.

