

GPS #: **0376**

Date Destroyed: **8/21/1995**

Date Revised:

Benchmark Designation:

OCS Index Map: **5LA**

Page/Grid: **889/J-5**

City / Location: **Irvine**

Scale Factor: **0.99996760**

Ellipsoid Red. Factor: **0.99999661**

Combination Factor: **0.99996420**

Convergence Angle: **-00 52 26.91003**

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.

Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 37 53.87581	117 50 26.67767	2177147.926	6077476.897	70.932
2007.00	33 37 53.89227	117 50 26.69461	2177149.61	6077475.49	

References: RSB 119/25-29, RSB 150/10-23

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD REBAR DOWN 1.0' IN WELL MONUMENT, IN THE INTER OF BONITA CANYON DR. AND COYOTE CANYON RD., 5' S'LY FROM EDGE OF PAVED SHOULDER ON PROD OF COYOTE CANYON RD.