

GPS #: 0476

Date Destroyed: 3/13/2002

Date Revised:

Benchmark Designation:

OCS Index Map: 1L

Page/Grid: 740/B-5

City / Location: Yorba Linda

Scale Factor: 0.99999952

Ellipsoid Red. Factor: 0.99998910

Combination Factor: 0.99998862

Convergence Angle: -00 51 38.21102

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 52 49.66058	117 48 58.05625	2267572.410	6086329.287	227.775
2007.00	33 52 49.67708	117 48 58.07291	2267574.10	6086327.91	

References: MM 489/20-22, RSB 149/1-9

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD PUNCHED SPIKE AND "LS 3997" ALUMINUM WASHER FLUSH IN A.C. SURFACE AT THE CENTERLINE INTER OF LAKEVIEW AVE. AND BUENA VISTA AVE.

NO
LOCATION
MAP