

HORIZONTAL CONTROL DATA SHEET CCS83, ZONE VI



GPS #: 2598

Date Destroyed: 6/16/2003

Date Revised: 6/8/1999

Benchmark Designation: AP-08-99
OCS Index Map: 6LB

Page/Grid: 922/G-6

City / Location: Unin., Orange County

Scale Factor: 0.99996238

Ellipsoid Red. Factor: 0.99997526

Combination Factor: 0.99993764

Convergence Angle: -00 45 27.57604

Factors and Convergance Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 34 00.92621	117 37 43.58290	2152685.091	6141681.043	516.997
2007.00	33 34 00.94304	117 37 43.59868	2152686.81	6141679.73	

References: OCS SURVEY FILE # 989GL9179

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: DESCRIBED BY OCS 2/25/99 - FOUND 3 ¾" OCS ALUMINUM BENCHMARK DISK STAMPED "AP-08-99" SET IN 6" x 6" CONCRETE POST, UP 0.2' FROM DIRT SURFACE. TO REACH THE BENCHMARK FROM THE INTERSECTION OF OSO PARKWAY AND ANTONIO PARKWAY, PROCEED SOUTHERLY 1.25 MILES ALONG ANTONIO PARKWAY (NORTHERLY 3.5 MILES FROM ORTEGA HIGHWAY). SAID MONUMENT BEING 3' EASTERLY FROM TOP OF AC CURB OF THE NORTHBOUND LANES, 23' SOUTHERLY FROM THE BEGINNING OF A CONCRETE "V" DITCH, WITNESSED BY 2 ORANGE CARSONITE WITNESS POSTS.

