

GPS #: **3166R1**

Date Destroyed:
Date Revised: 2/4/2002
Benchmark Designation:
OCS Index Map: 2L
Page/Grid: 800/D-1
City / Location: Unin., Orange County

Scale Factor: 0.99998857
Ellipsoid Red. Factor: 0.99998940
Combination Factor: 0.99997796
Convergence Angle: -00 51 08.07546

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 48 36.08046	117 48 03.21802	2241872.958	6090571.023	221.630
2007.00	33 48 36.09649	117 48 03.23493	2241874.60	6090569.62	

References: RSB 121/14-17, RSB 149/10-20, SURVEY FILE # 012PW-GL594020

Description:

NOTE: POSITION WAS UPDATED 2/4/02. ORIGINAL POSITION DID NOT FIT MONUMENT LOCATION. FD PUNCHED HEX BAR, DOWN 1.4' IN O.C.S. WELL MONUMENT. STATION IS LOCATED AT THE CENTERLINE INTER OF HEWES ST. AND VILLA PARK RD./SANTIAGO CANYON RD.

