

HORIZONTAL CONTROL DATA SHEET CCS83, ZONE VI



GPS #: 3237R2

Date Destroyed: 1/6/2012

Date Revised: 7/7/2011

Benchmark Designation:

OCS Index Map: 5LB Page/Grid: 800/H-5

City / Location: Unin., Orange County

 Scale Factor:
 0.99998395

 Ellipsoid Red. Factor:
 0.99997054

 Combination Factor:
 0.99995449

 Convergence Angle:
 -00 50 09.59927

Factors and Convergance Angle based on the 1991.35 Epoch Adjustment positions.

<u> </u>	5
	>

Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 46 37.02880	117 46 16.80258	2229707.794	6099373.821	R1
2007.00	33 46 37.04498	117 46 16.81874	2229709.45	6099372.48	

References: RSB 150/24-35, SURVEY FILE # 989OP5462, CR 2011-2604, CR 2012-0237

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD GEAR SPIKE AND WASHER STAMPED "LS 5921" IN LIEU OF LARGE PUNCHED NAIL (SPIKE) DOWN 0.15' IN A.C. MONUMENT WAS RESET USING ORIGINAL TIES PER CR 2011-2604. STATION IS LOCATED AT APPARENT CENTERLINE INTER OF COWAN HEIGHTS DR. AND RANGEVIEW DR.

