

GPS #: 3731R1

Date Destroyed: 6/29/2004

Date Revised: 4/2/2001

Benchmark Designation:

OCS Index Map: 3L

Page/Grid: 797/G-1

City / Location: Stanton

Scale Factor: 0.99998857

Ellipsoid Red. Factor: 1.00000308

Combination Factor: 0.99999164

Convergence Angle: -00 58 03.13442

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 48 35.96791	118 00 38.53143	2242873.664	6026845.387	
2007.00	33 48 35.98384	118 00 38.54877	2242875.30	6026843.95	

References: RSB 149/21-36, CR 2001-0659

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD BRASS NAIL WITH 1 1/4" WASHER STAMPED "LS 5458" FLUSH IN POUR ROCK IN LIEU OF 1/2" STEEL ROD. MONUMENT WAS RESET PER CORNER RECORD # 2001-659. MONUMENT IS LOCATED AT THE VISUAL CENTERLINE INTER OF CERRITOS AVE. AND KNOTT AVE.

NO
LOCATION
MAP