

**GPS #:** 4525

**Date Destroyed:** 5/7/2003

**Date Revised:**

**Benchmark Designation:**

**OCS Index Map:** 6LB

**Page/Grid:** 893/F-1

**City / Location:** Rancho Santa Margarita

**Scale Factor:** 0.99996935

**Ellipsoid Red. Factor:** 0.99993305

**Combination Factor:** 0.99990241

**Convergence Angle:** -00 43 07.81131

*Factors and Convergence Angle based on  
the 1991.35 Epoch Adjustment positions.*

| Epoch Adjustment | Latitude       | Longitude       | Northing (ft) | Easting (ft) | Ellipsoid Height (ft) |
|------------------|----------------|-----------------|---------------|--------------|-----------------------|
| 1991.35          | 33 39 01.69552 | 117 33 29.24212 | 2182806.691   | 6163581.928  | 1399.098              |
| 2007.00          | 33 39 01.71228 | 117 33 29.25737 | 2182808.40    | 6163580.66   |                       |

**References:** RSB 151/1-11

**Description:**

REPORTED DESTROYED (SEE DATE IN DESTROYED  
BOX) - ORIGINAL DESCRIPTION BEING: FD PK NAIL  
FLUSH IN A.C. SURFACE, IN THE APPARENT RADIUS  
POINT OF THE BROOKSEED DR. CUL-DE-SAC.