

GPS #: 4557

Date Destroyed: 7/26/2000

Date Revised:

Benchmark Designation:

OCS Index Map: 6LB

Page/Grid: 893/D-3

City / Location: Dove Canyon

Scale Factor: 0.99996829

Ellipsoid Red. Factor: 0.99994869

Combination Factor: 0.99991698

Convergence Angle: -00 43 35.69464

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 38 21.15679	117 34 19.98358	2178763.497	6159240.884	1072.262
2007.00	33 38 21.17359	117 34 19.99879	2178765.21	6159239.62	

References: RSB 151/1-11

Description:

REPORTED DESTROYED (SEE DATE IN DESTROYED BOX) - ORIGINAL DESCRIPTION BEING: FD SMALL PK NAIL FLUSH IN A.C., AT THE APPARENT CENTERLINE INTER OF DOVE CANYON DR. AND SYCAMORE CANYON DR.

NO
LOCATION
MAP