

GPS #: **5190R1**

Date Destroyed:

Date Revised: 2/25/2013

Benchmark Designation:

OCS Index Map: 1L

Page/Grid: 740/B-3

City / Location: Yorba Linda

Scale Factor: 1.00000250

Ellipsoid Red. Factor: 0.99998533

Combination Factor: 0.99998783

Convergence Angle: -00 51 45.92445

Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.

No PHOTO

Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35	33 53 53.04843	117 49 12.09302	2273997.142	6085242.439	
2007.00	33 53 53.06491	117 49 12.10979	2273998.83	6085241.05	

References: RSB 149/1-9, CR 2011-2516, CR 2012-0621

Description:

FD GEAR SPIKE WITH WASHER STAMPED "LS 5411", FLUSH, PER CR 2012-0621 IN LIEU OF, PUNCHED SPIKE AND WASHER AT THE APPARENT CENTERLINE INTER OF LA ENTRADA DR. AND EUREKA AVE.

