

**GPS #:** 6025

**Date Destroyed:** 10/20/2013

**Date Revised:**

**Benchmark Designation:**

**OCS Index Map:** 5LA

**Page/Grid:** 829/G-3

**City / Location:** Santa Ana

**Scale Factor:** 0.99998029

**Ellipsoid Red. Factor:** 0.99999933

**Combination Factor:** 0.99997962

**Convergence Angle:** -00 53 05.92570

*Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.*

| Epoch Adjustment | Latitude       | Longitude       | Northing (ft) | Easting (ft) | Ellipsoid Height (ft) |
|------------------|----------------|-----------------|---------------|--------------|-----------------------|
| 1991.35          | 33 44 55.99561 | 117 51 37.67753 | 2219903.086   | 6072133.361  | 13.940                |
| 2007.00          | 33 44 56.01197 | 117 51 37.69406 | 2219904.76    | 6072131.99   |                       |

**References:** RSB 150/10-23

**Description:**

REPORTED DESTROYED ORIGINAL MONUMENT  
BEING FD PK NAIL AND SANTA ANA SURVEY TAG,  
FLUSH IN A.C., STATION IS LOCATED AT THE  
APPARENT CENTERLINE INTER OF 5th ST. AND  
LACY ST.