

## GPS #: PRADO-88-11

Date Destroyed:

Date Revised: 4/15/2016

Benchmark Designation:

OCS Index Map:

Page/Grid:

City / Location: Prado Basin Area.

Scale Factor: 1.00001236

Ellipsoid Red. Factor: 0.99997778

Combination Factor: 0.99999015

Convergence Angle: -00 45 36.12

*Factors and Convergence Angle based on the 1991.35 Epoch Adjustment positions.*



Epoch Adjustment	Latitude	Longitude	Northing (ft)	Easting (ft)	Ellipsoid Height (ft)
1991.35			0.000	0.000	
2007.00	33 57 10.45701	117 37 59.13636	2293147.68	6142228.22	464.38

References: 2015 Prado Basin GPS Survey.

### Description:

FOUND 3 3/4" OCS ALUMINUM BENCHMARK DISK "PRADO-88-11" SET IN CONCRETE COLLAR. STATION IS LOCATED ALONG THE W'LY SIDE OF CHINO-CORONA ROAD 0.3 MILES S'LY OF PINE AVE. NEAR THE NE'LY CORNER OF THE WOMEN'S REHABILITATION CENTER. 30.6' W'LY OF THE CENTERLINE CHINO-CORONA ROAD, 4.2' W'LY OF P.P. #4019018E.

